
Water Tank Inspection and Cleaning



Inspection / Cleaning

Project Location: Hobe Sound, Florida

UESI teamed with several consulting engineering companies to provide divers, equipment and video systems to support and perform the underwater inspection and report for interior and exterior of six water storage tanks owned by a utility company. The tanks were not drained for the inspections. UESI also performed sediment removal utilizing a 3-inch-diameter suction line.

Completion Date: February 2012

UESI Job Number: COM2011251