

Onagawa Nuclear Power Station



Underwater Engineering Services, Inc.



Nuclear Diving Services

Client/Owner: IHI Plant Construction Co., Ltd.

Project Location: Japan

The general scope of work included cleaning (desludging), coatings inspection and repair, VT 1 & 3 inspection, ISI (in service inspection), earthquake inspection assessment and removal of ECCS suction strainers, installation of caps/plugs and reinstallation of ECCS suction strainers in the Onagawa Unit 3 Suppression Chamber.

Completion Date: November 2010